



Note: +5 and Ground for Hall Sensors
 can also be taken from UPC board
 to save wires to motor.
 This powers Hall sensors and position encoder from
 same power source.

